

Message

From: Dan Johnson [DanJohnson@florencecopper.com]
Sent: 3/7/2019 4:38:54 PM
To: Rumrill, Nancy [Rumrill.Nancy@epa.gov]
CC: Coffman, Joel [Coffman.Joel@epa.gov]; Rao, Kate [Rao.kate@epa.gov]
Subject: RE: FC Temperature Logging results for wells R-07 and R-08
Attachments: ATT00001.txt

Good Morning Nancy,

Thank you for your comments below. We will either make those corrections going forward or transmit a response with an explanation why a particular item was not provided.

Best Regards,

Dan Johnson VP | General Manager



Florence Copper Inc.
1575 W. Hunt Highway Florence AZ USA 85132
C 520-233-1930 T 520-374-3984 F 520-374-3999
E danjohnson@florencecopper.com Web florencecopper.com

From: Rumrill, Nancy [mailto:Rumrill.Nancy@epa.gov]
Sent: March-06-19 5:26 PM
To: Dan Johnson
Cc: Coffman, Joel; Rao, Kate
Subject: FC Temperature Logging results for wells R-07 and R-08

Hi Dan,

These are our comments on R-07 and R-08 Temperature Logging results that you provided in the February 15, 2019 letter. There are no significant anomalies in the temperature records of either well and no indication of fluid movement in the cemented annulus of each well. Therefore, Part 2 mechanical integrity is confirmed in both wells based on the temperature logs run in the R-07 and R-08 wells on February 1, 2019.

Some items are missing per the EPA Region 9 Temperature Logging Requirements as provided in Appendix D of the permit. The logs lack headings and the pertinent information usually provided in the headings such as well name, location, elevations, dates, total shut-in times, etc. The right-hand tracks of each log omit the required differential temperature plots. The left-hand track omits the collar locator log. The depth to the base of the lowermost USDW is not provided. However, the most critical information about the logs was provided in the February 15, 2019 letter from Florence Copper. Those missing components of the temperature log should be added to temperature logs run in the future.

Thanks, Nancy

~~~~~

Nancy Rumrill ([rumrill.nancy@epa.gov](mailto:rumrill.nancy@epa.gov))

Drinking Water Protection Section (WTR-3-2)

US EPA, Region IX

75 Hawthorne St.

San Francisco, CA 94105

Phone (415) 972-3293

---

"Notice Regarding Transmission

This message is intended only for the person(s) to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is prohibited. Please notify us of the error in communication by telephone (778-373-4533) or by return e-mail and destroy all copies of this communication. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Taseko Mines Limited or any affiliated or associated company. The recipient should check this email and any attachments for the presence of viruses. Neither Taseko Mines Limited nor any affiliated or associated company accepts any liability for any damage caused by any virus transmitted by this email. Thank you "